


Soils and Foundations

東日本大震災特集号 DVD発刊のお知らせ



2011年3月11日の東日本大震災発生に伴い、当学会から発行しております英文論文集「Soils and Foundations」では平成24年10月号 (Vol.52, No.5) をその特集号に充て、発刊しました。

<http://www.sciencedirect.com/science/journal/00380806/52/5>

この度、地盤工学会ではこの特集号に写真、動画、論文9編を追加した総集編DVDを作成し、2015年1月に発刊のはこびとなりました。広く防災に携わる人々にとって有用な資料として本書をご活用いただければ幸いです。

【ご注文方法】

ショッピングサイトまたはFAX, Eメールで承っています。

ショッピングサイト:

http://www.jgs-shopping.net/products/detail.php?product_id=1000904545

FAX: 03-3946-8678 (注文書: <http://www.jgs-shopping.net/pdf/fax.pdf>)

e-mail: jigyo@jiban.or.jp (注文専用)

【問合せ先】

公益社団法人地盤工学会 総務・出版事業チーム

TEL : 03-3946-8672 e-mail : kaishi@jiban.or.jp

担当 : 小澤



“Soils and Foundations Special Issue on Geotechnical Aspects of the 2011 off the Pacific Coast of Tohoku Earthquake”

DVD判, 2015年1月発行

価格: 3,500円 (税込) 送料: 450円 (税込)

CONTENTS

Picture: Photographs on the 2011 off the Pacific Coast of Tohoku Earthquake damage

Movie: Movies on the 2011 off the Pacific Coast of Tohoku Earthquake damage

Manuscript:

1. Frontispiece (Photographs on the 2011 off the Pacific Coast of Tohoku Earthquake damage (Special issue on geotechnical aspects of

the 2011 off the Pacific Coast of Tohoku Earthquake, Soils and Foundations))

2. Preface (Message from the President of the Japanese Geotechnical Society), by *T. Sueoka*
3. Ground motion characteristics during the 2011 off the Pacific Coast of Tohoku Earthquake, by *H. Goto and H. Morikawa*
4. The impact of the 2011 Tohoku earthquake tsunami disaster and implications to the reconstruction, by *S. Koshimura, S. Hayashi and H. Gokon*
5. Damage statistics (Summary of the 2011 off the Pacific Coast of Tohoku Earthquake damage), by *M. Kazama and T. Noda*
6. Characteristics of liquefaction in Tokyo Bay area by the 2011 Great East Japan Earthquake, by *S. Yasuda, K. Harada, K. Ishikawa and Y. Kanemaru*
7. Liquefaction in the Kanto region during the 2011 off the Pacific coast of Tohoku earthquake, by *I. Towhata, S. Maruyama, K. Kasuda, J. Koseki, K. Wakamatsu, H. Kiku, T. Kiyota, S. Yasuda, Y. Taguchi, S. Aoyama and T. Hayashida*
8. Liquefaction in Tohoku district during the 2011 off the Pacific coast of Tohoku Earthquake, by *A. Yamaguchi, T. Mori, M. Kazama and N. Yoshida*
9. Effect of earthquake ground motions on soil liquefaction, by *S. Unjoh, M. Kaneko, S. Kataoka, K. Nagaya and K. Matsuoka*
10. Seismic design of highway bridge foundations with the effects of liquefaction since the 1995 Kobe earthquake, by *K. Tamura*
11. Earthquake-induced landslides: distribution, motion and mechanisms, by *S. Nakamura, A. Wakai, J. Umemura, H. Sugimoto and T. Takeshi*
12. Wide-area land subsidence caused by the "the 2011 Off the Pacific Coast of Tohoku Earthquake", by *T. Imakiire and M. Koarai*
13. Geo-environmental issues induced by the 2011 off the Pacific Coast of Tohoku Earthquake and tsunami, by *T. Inui, T. Yasutaka, K. Endo and T. Katsumi*
14. Damage to railway earth structures and foundations caused by the 2011 off the Pacific Coast of Tohoku Earthquake, by *J. Koseki, M. Koda, S. Matsuo, H. Takasaki and T. Fujiwara*
15. Damage patterns of river embankments due to the 2011 off the Pacific Coast of Tohoku Earthquake and a numerical modeling of the deformation of river embankments with a clayey subsoil layer, by *F. Oka, P. Tsai, S. Kimoto and R. Kato*
16. Damage to coastal structures, by *Y. Kikuchi, T. Sugano, A. Nozu, E. Kohama and K. Shimosako*
17. The damage to hillside embankments in Sendai city during The 2011 off the Pacific Coast of Tohoku Earthquake, by *T. Mori, Y. Tobita and T. Okimura*
18. Building damage during the 2011 off the Pacific coast of Tohoku Earthquake, by *M. Motosaka and K. Mitsuji*
19. Safety inspections and seismic behavior of embankment dams during the 2011 off the Pacific Coast of Tohoku earthquake, by *Y. Yamaguchi, M. Kondo and T. Kobori*
20. Damage to agricultural facilities, by *Y. Mohri, S. Masukawa, T. Hori and M. Ariyoshi*
21. Damage to Sewage Systems Caused by the Great East Japan Earthquake, and Governmental Policy, by *M. Matsuhashi, I. Tsushima, W. Fukatani and T. Yokota*
22. Building damage associated with geotechnical problems in the 2011 Tohoku Pacific Earthquake, by *K. Tokimatsu, S. Tamura, H. Suzuki and K. Katsumata*
23. Slope failures in residential land on valley fills in Yamamoto town, by *M. Hyodo, R.P. Orense, S. Noda, S. Furukawa and T. Furui*
24. Soil liquefaction observed at the lower stream of Tonegawa river during the 2011 off the Pacific Coast of Tohoku Earthquake, by *Y. Tsukamoto, S. Kawabe and T. Kokusho*
25. Seismic behavior of piled raft with ground improvement supporting a base-isolated building on soft ground in Tokyo, by *K. Yamashita, J. Hamada, S. Onimaru and M. Higashino*